

Audi Phone Preparation with Bluetooth®

Tested Compatible Cell Phones

Phone Manufacturer	Phone Model	Type ⁺	Audi Cradle Part # *	Phonebook Download ³	Minimum Firmware ⁴	First Model Year	
>	Motorola	V3 RAZR	GSM	Not available	Yes	T-Mobile 42.09R	2006
	"	"	"	"	Yes	Cingular 41.C3R	2006
	V3c RAZR	CDMA	Not available	Yes	01.0F.02	2007	
	E815	CDMA	Not available	Yes	8720_01.17.03	2007	
	V710	CDMA	4F0 051 435 C	Yes	8700_01.40.0R	2006	
	V620	GSM	}	4F0 051 435 B ⁷	Yes	G_0E.65.25R	2005 ⁷
	V600	GSM			Yes	G_0B.09.2FR	2005 ⁷
	V557	GSM			Yes	G_08.28.3DR	2007
	V551	GSM			Yes	G_08.17.0FR	2005 ⁷
	V540	GSM			Yes	G_08.18.40R	2007
	V505	GSM			Yes	G_0B.09.4AR	2005 ⁷
	V500	GSM			Yes	G_0B.09.17R	2005 ⁷
	V400 ¹	GSM			Yes	G_0B.09.2FR_A1	2005 ⁷
	V300 ¹	GSM			Yes	G_0B.09.3AR_A	2005 ⁷
i605	Nextel	Not available			No	R2F.00.00	2007
V60 (c,i,s,x) ^{1,2}	all	4F0 051 435 E	Yes	-	2005		
>	LG	VX8100	CDMA	Not Available	No	T81VZ07	2007
	AX355	CDMA	Not Available	No	T35ATV01	2007	
>	Nokia	6820	GSM	Not Available	No	V04.46	2005
	6230	GSM	Not Available	Yes	V05.24	2005 ⁶	
>	Palm	Treo 650 GSM	GSM	Not Available	"Favorites" only	1.13 ⁵	2006
>	Research In Motion (RIM)	BlackBerry 7100	GSM	Not Available	No	4.0.0.198	2006
	BlackBerry 7130e	CDMA	Not Available	No	V4.1	2007	
	BlackBerry 7290	GSM	Not Available	No	4.0.0.198	2006	
>	Sanyo	SCP-6600 Katana	CDMA	Not Available	Yes	1.000SP	2007
>	Samsung	A960	CDMA	Not Available	Yes	ZA09	2007
	A900	CDMA	Not Available	Yes	ZD12	2007	
	A940	CDMA	Not Available	Yes	ZA13	2007	
>	Siemens	S56	GSM	Not Available	Yes (SIM)	20	2005
	S66	GSM	Not Available	Yes (SIM)	48	2005 ⁶	
>	Sony Ericsson	T610	GSM	}	Yes (SIM)	R3A	2005 ⁶
	T616	GSM	Yes (SIM)		R1B	2005	
	T630	GSM	4F0 051 435 D		Yes (SIM)	R3C	2005 ⁶
	T637	GSM	Yes (SIM)		R5A	2006	
	T637	GSM	Yes (SIM)		R3A	2005 ⁶	

Phones listed above have been tested for compatibility with the Audi Phone Preparation. Other Bluetooth®-equipped phones may have various levels of compatibility with Audi vehicles, but are not supported by Audi.

+ **Major GSM carriers: Cingular and T-Mobile. Major CDMA carriers: Alltel, Sprint and Verizon.**

* Older phone cradles (for vehicles equipped with Audi Telematics by OnStar®) will not function in combination with the new Audi Phone Preparation. Please use the new cradle part numbers listed on this sheet.

1 These phones are not Bluetooth®-equipped, but will work with the Audi Phone Preparation in conjunction with the appropriate phone cradle.

2 V60 "street" phones will not work; only Audi OEM Versions sold through an Audi dealer are compatible.

3 CDMA phones: numbers stored in the phonebook are synchronized with the vehicle.

GSM phones: numbers stored in the phonebook and the SIM-card are synchronized, except where noted.

4 Older phone firmware may not be fully compatible and may cause system instability; contact your phone provider to be sure the latest firmware is loaded in your phone.

5 Minimum v1.15 for Cingular version. Software downloads available at www.palm.com

6 MY2005 A8 models without Audi Telematics by OnStar® equipment are compatible.

MY2005 A6 models after VIN: 4F_070061 are compatible.

7 Audi strongly recommends the use of the Audi phone cradle for optimum performance in MY2005 vehicles.

> **Change from previous chart version**

Audi of America, Inc. and Audi Canada believe the information presented to be correct at the time of publication. All specifications are subject to revision. Check the www.audiusa.com or www.audicanada.ca websites regularly for updates to this matrix. Bluetooth® is a registered trademark of the Bluetooth SIG, Inc.. OnStar® is a registered trademark of OnStar Corporation.

rev. 08/23/2006